



**Jobs for Specific Trades / Externals**

Area	Job	Volunteer or Contractor	Priority Level	Date Started	Date Completed	Completed By: Name and	Signed off by BMC Staff	Notes
<b>Contractors/Externals</b>								
General	Activity shirts etc.	External	High	Mar-23				Email gone out for sizes
Grimley	Thermostat for Grimley boiler	External	High					
Block House	Door replacements and access to fuse boards	External	High					
Rhodes	Reroute gas pipe from under building	Contractor	Medium					
Toilet block or Carlton	Replacement boiler	External						
Track	Surface lower part of track to car park gate	Contractor	Low					
Septic Tank	Cut Down tree within enclosure	contractor	Low					
<b>Plumbers Skilled (CS)</b>								
All of Site	Replace / Repair site taps	Volunteer - CS (Skilled)						Always ongoing
Survival	Wash up facility	Volunteer - CS (Skilled)	Low					
Clewer (Wardens)	Connect Tray to drain	Volunteer - CS (Skilled)						
Clewer (Wardens)	Silicone Shower	Volunteer - CS (Skilled)						
Eaton	Panel disabled toilet area and reroute drains	Volunteer - CS (Skilled)	Low					

<b>Eaton</b>	Toilet to fit / Repair	Volunteer - CS (Skilled)		17/6/23	17/6/23	CS (BN)	JPR	
<b>Eaton</b>	re-direct sink waste to disabled and connect to drain	Volunteer - CS (Skilled)						
<b>Eaton</b>	Fit mixers from Carlton kitchen	Volunteer - CS (Skilled)						
<b>Shop/Eaton</b>	Take back service pipes from old caravan	Volunteer - CS (Skilled)	Low					
<b>Carlton</b>	Replace the showers	Volunteer - CS (Skilled)	low					
<b>Carlton</b>	Re fit the toilet and basin	Volunteer - CS (Skilled)						
<b>Carlton</b>	Change Kitchen Taps	Volunteer - CS (Skilled)						
<b>Carlton</b>	Check upstairs radiators	Volunteer - CS (Skilled)						
<b>Rhodes</b>	Kitchen Radiator Not Working	Volunteer - CS (Skilled)		4/5/23	4/5/23	CS (BN)	JPR	
<b>Rhodes</b>	Radiator leaking (Bedroom)	Volunteer - CS (Skilled)		4/5/23	4/5/23	CS (BN)	JPR	
<b>Rhodes</b>	Toilet Leaking in Gents	Volunteer - CS (Skilled)						No Leak!
<b>Rhodes</b>	Urinal needs replacing	Volunteer - CS (Skilled)						
<b>Main Toilet Block</b>	Urinal - Continued feed into cistern	Volunteer - CS (Skilled)						
<b>Main Toilet Block</b>	Test all 4 showers	Volunteer - CS (Skilled)						
<b>2nd Toilet Block</b>	Replace plugs	Volunteer - CS (Skilled)	Medium					
<b>Electrician Skilled (LH)</b>								

<b>All Site</b>	Electrical infrastructure upgrade across site	Volunteer (LH) and contractor	Medium						50% complete
<b>Lower Track</b>	Replace track lighting	Volunteer - LH (Skilled)	Low						Started 25% complete
<b>Carlton</b>	Replace lighting in upstairs garage	Volunteer - LH (Skilled)	Medium						
<b>Cub Shelter</b>	Replace lighting in shelter (See EHIC)	Volunteer - LH (Skilled)							
<b>Grimley / Carlton</b>	Smoke Detectors Failure - To be checked please	Volunteer - LH (Skilled)							PP3 battery needed in Grimley
<b>Eaton</b>	Bedroom Light	Volunteer - LH (Skilled)							
<b>Rhodes</b>	Replace cooker extractor hood	Volunteer - LH (Skilled)	High						
<b>Skilled - Volunteers</b>									
<b>Ranges</b>	Benches to be put in Archery Shelter	Volunteers	High						
<b>Wood Pile</b>	Scrape and level pile Put in fence Posts Build fencing	Volunteers & External	High						
<b>Campsites</b>	Complete Base of Mary Bushell Shelter	Volunteers	High						
<b>Campsites</b>	Repair Fire bases	Volunteers (Skilled) / External (College Students)	High						
<b>Clewer</b>	Decking to rear of Clewer (warden)	Volunteers (Skilled)	High						
<b>Climbing Wall</b>	Repair - Brackets for boards and gate to abseiling	Activity Team	Medium						
<b>Development Field</b>	Gate Access	Volunteer / External (Skilled)	Low						
<b>Clewer</b>	Add a railing to steps on crew side	Volunteer (Skilled)	Low						

<b>Clewer</b>	Crew side decking	Volunteer (Skilled)	Low					
<b>Eaton</b>	Clad the Rear Wall	Volunteer - Skilled	Medium					
<b>Climbing Tower</b>	Re paint the tower - With Correct outdoor paint	Volunteer - Activities - Skilled	Medium					
<b>Eaton</b>	Disabled toilet ceiling replacement	Volunteer - Skilled	Low					
<b>2nd Toilet Block</b>	Tile the skirting area in both sections	Volunteer - Skilled	Low					
<b>Rhodes Hut</b>	Repair to gable end wall (Cladding exterior)	Volunteer - Skilled	Medium					
<b>Grimley</b>	Reclad wall over kitchen - High reach	Volunteer - Skilled	Medium					